

**Amendments to the Drawings:**

The attached sheets of drawings include changes to Figs. 1-4. The sheets containing Figs. 1-4 replace the original sheets that included Figs. 1-4. In Fig. 1, references to cable protruding end 66 and pockets 18 and 24 have been added. In Fig. 2, reference to element side support bracket brace 78 has been added, and the number identifying adjustment hole 76 has been corrected by replacing the incorrect number, 86. In Fig. 3, references to cable protruding end 66 and crank 82 have been added, and reference 78 has been deleted. In Fig. 4, reference to element 32 has been deleted.

Attachments:    Replacement Sheets

                        Annotated Marked-Up Drawings



Appl. No. 09/977,734  
Amdt. Dated Feb. 25, 2004  
Reply to Office Action of Jan. 15, 2004  
**Replacement Sheet**




Fig. 1



Appl. No. 09/977,734  
Amdt. Dated Feb. 25, 2004  
Reply to Office Action of Jan. 15, 2004  
Replacement Sheet




Fig. 2



Appl. No. 09/977,734  
Amtd. Dated Feb. 25, 2004  
Reply to Office Action of Jan. 15, 2004  
**Replacement Sheet**




Fig. 3

Appl. No. 09/977,734  
Amtd. Dated Feb. 25, 2004  
Reply to Office Action of Jan. 15, 2004  
**Replacement Sheet**

